


Model 212
(Countries with high dust levels)

- Service A
- Service B
- Plus package
- For every service (equipment specific)
- Once at 3,000 km (1,850 mi)
- Service 3 at every service
- Service 4 every 2 years
- Service 8 every 50,000 km (31,000 mi) / 3 years
- Service 8 every 75,000 km (46,500 miles)/4 years
- Service 10 every 50,000 km (31,000 miles)/3 years
- Service 11 every 75,000 km (46,500 mi) / 4 years
- Service 11 every 250,000 km (155,000 miles)/15 years
- Service 12 every 50,000 km (31,000 miles) / 3 years
- Service 12 every 75,000 km (46,500 miles) / 4 years
- Service 13 every 250,000 km (155,000 mi) / 15 years
- Service 15 at every Service B
- Service 20 once at 50,000 km (31,000 mi) / 3 years
- Service 20 every 100,000 km (62,000 mi) / 5 years
- Service 20 every 125,000 km (77,500 miles)/5 years



P00.00-4883-11

Customer Carsten Bøgh Poulsen Order number _____

VIN/license plate number WDD2120881A895039/BX39247 Current mileage 104.022km

Service code _____ Workshop code _____

Remaining distance _____ Remaining time _____

Oil type/viscosity WS-30 Completion time/date 2020-11-20

Service consultation performed at vehicle Yes No

Notes/explanations _____

The following activities are hereby confirmed:
- Completion of relevant service operations

Signature Carsten Bøgh Poulsen

A Completed		B		Input condition not OK:	⊗
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>				↓
		Service reception			
<input type="checkbox"/>	<input checked="" type="checkbox"/>	The completely edited reception report for service on vehicle is available	<input type="radio"/>	AP00.20-P-0009Z
		i To be performed by the Service Advisor (where market-specific conditions require). The service scope is only fully performed when all acceptance items and the maintenance items listed in the service sheet have been processed.			
		Brake system			
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Perform brake test and enter the result in the table	<input type="radio"/>	AP42.00-P-4290BA
		Vehicle exterior			
	<input checked="" type="checkbox"/>	Check exterior lights for proper operation	<input type="radio"/>	AP82.10-P-8252EW
	<input checked="" type="checkbox"/>	Check operation of headlamp range adjustment	<input type="radio"/>	AP82.10-P-8250EW
	<input checked="" type="checkbox"/>	Check and correct the adjustment of the headlamps	<input type="radio"/>	AP82.10-P-8260EW
		i On vehicles equipped with level control or Xenon or dynamic LED headlamps, adjustment of the headlamps is to be invoiced as an additional operation.			
		Vehicle interior			
	<input checked="" type="checkbox"/>	Check windshield wipers, windshield washer system and headlamp cleaning system for proper operation	<input type="radio"/>	AP82.30-P-8252EW
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Replace activated charcoal dust filter		AP83.00-P-8384EW
		Engine compartment			
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Clean water drain		AP82.35-P-8232A
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Brake system: Check fluid level	<input type="radio"/>	AP42.10-P-4210EW
	<input checked="" type="checkbox"/>	Check all visible parts in engine compartment for damage and leaks	<input type="radio"/>	AP00.20-P-0055EW
	<input checked="" type="checkbox"/>	Check visible area of poly-V belt for wear	<input type="radio"/>	AP13.22-P-1352EW
		Underside of vehicle			
	<input checked="" type="checkbox"/>	Check all visible parts of vehicle underside for damage and leakage	<input type="radio"/>	AP00.20-P-0054EW
	<input checked="" type="checkbox"/>	Check track rod and drag link linkage for play, check boots	<input type="radio"/>	AP46.00-P-4653EW
		i The country-specific regulations for mobility and body shell complaints apply.			

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Check front axle ball joint for play, check boots	<input type="radio"/>	AP33.20-P-3353EW
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Check condition of drive shaft and flexible couplings	<input type="radio"/>	AP41.10-P-4152EW
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Check tires for damage and cracking and enter result in table	<input type="radio"/>	AP40.10-P-4051EW
Tires					
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Plus package Correct tire pressure and enter set tire pressure in the table	<input type="radio"/>	AP40.15-P-4061A

<input type="checkbox"/>	<input checked="" type="checkbox"/>	Check TIREFIT tire sealant	<input type="radio"/>	AP40.10-P-4054R
			Vehicles fitted with TIREFIT		
			i Enter TIREFIT expiration date here:		
			i Replace TIREFIT, invoice as additional operation.		
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Check first aid kit	<input type="radio"/>	AP68.00-P-6850EW
			i Enter first aid kit expiration date here:		
			i Replace first-aid kit, invoice as an additional operation.		
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Check luggage compartment illumination for proper operation	<input type="radio"/>	
Engine compartment					
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Plus package Windshield washer system: Check/correct fluid level	<input type="radio"/>	AP82.35-P-8210EW
			i Use summer/winter cleaner as well as the mixing ratio to match the ambient temperature.		
Vehicle interior					
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Plus package Check lamps in the instrument cluster and interior illumination for proper operation	<input type="radio"/>	AP54.30-P-5453EW

<input type="checkbox"/>	<input checked="" type="checkbox"/>	<p>Engine compartment Service 3 at every service Engine: Change oil and filter</p> <p>.....</p> <p>Engine 276</p> <p>AP18.00-P-0101CWZ</p>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<p>Engine compartment Service 4 every 2 years Brake system: Replace brake fluid</p> <p>.....</p> <p><i>Skiftet 2019-03-22</i></p> <p>AP42.00-P-4280EW</p>

<input type="checkbox"/>	<input checked="" type="checkbox"/>	<p>Engine compartment Service 8 every 75,000 km (46,500 miles)/4 years Replace air filter element</p> <p>.....</p> <p>Engine 276.9</p> <p>AP09.10-P-0980MM</p>
--------------------------	-------------------------------------	---

<input type="checkbox"/>	<input type="checkbox"/>	<p>Vehicle interior Service 11 every 250,000 km (155,000 miles)/15 years Replace fuel filter</p> <p>.....</p> <p>Engine 156, 157, 271, 272, 273, 274, 276, 278</p> <p>AP47.20-P-0780EW</p>
--------------------------	--------------------------	---

<input type="checkbox"/>	<input checked="" type="checkbox"/>	Engine compartment Service 12 every 75,000 km (46,500 miles) / 4 years Replace spark plugs Engine 157, 272, 273, 276, 278	<i>Shyftet 2018-03-29</i> AP15.10-P-1580EW
<input type="checkbox"/>	<input type="checkbox"/>	Underside of vehicle Service 13 every 250,000 km (155,000 mi) / 15 years Replace main circuit coolant	AP20.00-P-2080EW

<input type="checkbox"/>	<input type="checkbox"/>	Underside of vehicle Service 20 once at 50,000 km (31,000 mi) / 3 years Automatic transmission: Carry out oil and filter change Transmission 722.9## #2 up to 834526 except 722.930/931/971	AP27.00-P-2702W
--------------------------	--------------------------	--	--	-----------------

<input type="checkbox"/>	<input type="checkbox"/>	Underside of vehicle Service 20 every 125,000 km (77,500 miles)/5 years Automatic transmission: Carry out oil and filter change Transmission 722.9## #2 as of 834527 except 722.930/931/971	AP27.00-P-2702W
--------------------------	--------------------------	--	--	-----------------

Brake values

	Left	Right
Front	<i>OK</i>	
Rear		
Parking brake		

Tire condition

	Right front	Left front	Right rear	Left rear
Condition OK.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Condition NOK.				

Set tire pressure in bar or psi

	Front axle	Rear axle	Spare wheel
bar/psi		<i>OK</i>	