


MODEL 117, 156, 164, 166, 169, 171, 172, 176, 197.3/4, 203, 204, 205, 207, 209, 211, 212, 216, 218, 219, 221, 222, 230, 231, 242, 245, 246, 251, 461, 463

Mark damaged areas in picture.

- K = Corrosion
- L = Paint damage
- D = Dent / deformation*
- F = Component missing*
- R = Crack/scratch*
- S = Stone chipping on windshield*
- X = Other:*
- Shown on model 212.2
- The items denoted by * are optional, for body shell complaints see reference documents.



P00.20-2748-11

Customer Poulsen
 VIN/license plate number BX39247
 Service code A5
 Remaining distance 9265
 Oil type/viscosity 0W-30 229.5
 Notes/explanations

Order number
 Current mileage ~~6020~~ 60687
 Workshop code 3DGG
 Remaining time -174
 Completion time/date 29/8-2018

- The following activities are hereby confirmed:
- Performance of all test/check items in the reception report
 - Correctness of defined service scope
 - Update of Digital Service Booklet (DSB), if available for veh. and market
 - Service report (DSB) for customers printed out/service booklet filled out

Signature Cank P...

		Input condition not OK:	⊗
Completed			⊗
<input checked="" type="checkbox"/>			⬇
<input checked="" type="checkbox"/>	Outside of vehicle Check condition of vehicle on outside	<u>OK</u>	○
<input checked="" type="checkbox"/>	Check condition of windshield	<u>OK</u>	○
<input checked="" type="checkbox"/>	Check condition of wiper blades	<u>OK</u>	○
	Engine compartment Check coolant level	<u>OK</u>	○

AP60.00-P-6048U
 AP67.10-P-6750A
 AP82.30-P-8253G
 AP20.30-P-2049U

i Note antifreeze protection type 30.

<input type="checkbox"/>	Tires, brake (enter into table) Check condition and tread depth of tires	OK	<input type="radio"/>	AP40.10-P-4052B
<input type="checkbox"/>	Assess condition of brake shoe	} MAY NEED REPLACEMENT	<input type="radio"/>	AP42.10-P-4248U
<input type="checkbox"/>	Assess condition of brake disks		<input type="radio"/>	AP42.10-P-4249U
<input type="checkbox"/>	Underside of vehicle Check condition of vehicle underside	OK	<input type="radio"/>	AP60.00-P-6049U
i Check is optional.				
<input type="checkbox"/>	Vehicle interior Check warning and function indicator lamps in instrument cluster	OK	<input type="radio"/>	AP54.30-P-5449U
<input type="checkbox"/>	Check horn for proper operation	OK	<input type="radio"/>	
<input type="checkbox"/>	Read out map data status from navigation system, check update			
	Card data status:			AP82.85-P-8249U
<input type="checkbox"/>	Read out maintenance data from instrument cluster, note and reset service indicator	✓		AP00.20-P-0049U
i If the service is not performed in full, reset the service indicator.				
<input type="checkbox"/>	Customer / vehicle-specific options (if available for model) Perform Plus package	OK		AP00.20-P-0048U
		<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		
<input type="checkbox"/>	Conduct additional operation "Fill up with AdBlue®"	N/A		
		<input type="checkbox"/> yes <input checked="" type="checkbox"/> no		
<input type="checkbox"/>	Perform operations that are not governed by the workshop code			
		<input type="checkbox"/> yes <input checked="" type="checkbox"/> no		AP00.20-P-0047U
i Driving aids ex factory and dust filter.				

Condition/tread depth of tires				
(Mark applicable field with x or optionally, enter tread depth)	Right front	Left front	Right rear	Left rear
Condition and tread depth OK.	✓	✓	✓	✓
Wear limit reached / exceeded	NO	NO	NO	NO
Unusual wear pattern	NO	NO	NO	NO
Max. tire age / mileage reached / exceeded (special protection only)	NO	NO	NO	NO

Condition of brake linings				
(Mark applicable field with x)	Right front	Left front	Right rear	Left rear
Condition in visible area OK.	x	x	x	x
Wear limit reached / exceeded	/	/	/	/
Soiled (oil, grease, etc.)/damaged	NO	NO	NO	NO

Condition of brake disks				
(Mark applicable field with x)	Right front	Left front	Right rear	Left rear
Condition in visible area OK.	x	x	x	x
Wear / damaged (e.g.: score marks, cracks, corrosion, chippings, deeply contoured ridging with steel brake disks)	NO	NO	NO	NO
Soiled (oil, grease, etc.)	NO	NO	NO	NO