


0115546971

Mercedes-Benz
E 350

EXTERIOR

ROOF

1. Roof; Scratched; Over 25mm Thru Paint



This diagram is a representation of the vehicle and does not accurately reflect the location of each piece of damage. Minor items are listed but are not reflected in the diagram. While every effort is made to ensure that the information contained in BCA Condition report is correct at the time of publication (22/02/2018 12:40), BCA reserves the right to make changes to vehicles available in our auctions, and any other information contained herein. Updated information, if any, is available upon request from BCA.



EXTERIOR - ROOF
Roof; Scratched; Over 25mm Thru Paint

This diagram is a representation of the vehicle and does not accurately reflect the location of each piece of damage. Minor items are listed but are not reflected in the diagram. While every effort is made to ensure that the information contained in BCA Condition report is correct at the time of publication (22/02/2018 12:40), BCA reserves the right to make changes to vehicles available in our auctions, and any other information contained herein. Updated information, if any, is available upon request from BCA.